


Z30 Scale Weight Configuration Barcodes



Pounds (1)



Low Vibration Sensitivity (1)

If you make a mistake or the calibration fails, scan the barcode below to reset the settings and start the process again:



Reset Settings